

Reference Number	TV-101614
Date	10/16/14
Product	TELEVISION
Affected Models	40D3505


Subject: Faulty Wall Columns

Background: A part upgrade has been made to the wall columns. In order to update, please follow the steps below.

Replacement Part:


Please visit <u>www.encompass.com</u> Upgraded part Number: 0530004746 Upgraded part Name: Wall Column

Quantity Needed: (4)



Repair Procedure:

Step 1: Remove the back cover.



for use only by persons qualified for the specific tasks xperience, are capable of identifying risks and avoiding sonnel should repair products powered by electricity. Any er than qualified personnel could result in serious injury or at your sole risk. This information is subject to change or plied, regarding the accuracy or completeness of this

nd technical information.


Visit our web site at www.haier.com/usa for more information about our products and company.



Step 2: Remove the two screws from the corner of the wall column



Step 3: Remove the old wall column and insert the newly upgraded sleeve. Repeat this step for all 4 sleeves.



Step 4: Reinstall the rear cover

This material is published for informational purposes only and intended for use only by persons qualified for the specific tasks shown. Qualified personnel are those who, based on their training and experience, are capable of identifying risks and avoiding possible hazards when handling or servicing a product. Only qualified personnel should repair products powered by electricity. Any attempt to handle, service or repair the product or products by anyone other than qualified personnel could result in serious injury or death. You agree that your use of and dependence on this information is at your sole risk. This information is subject to change or update without notice. There are no warranties, either expressed or implied, regarding the accuracy or completeness of this information.

Log into http://tsp.haier.net for parts and technical information.